



Phil's Pro Auto Service

707 12th Street
Greeley, CO 80631
Phone: (970) 353-2739 | Fax: (970) 356-0478
E-mail: Jon@philsprouauto.com
Website: www.philsprouauto.com

Invoice Preview

Bill To Mills, Harry
2358 50th Avenue
Greeley, Colorado 80634
USA

Cell (970) 290-0550
Email harryzaims@gmail.com

Work Order # 58510
Service Advisor Jon White
Technician Terry Snyder

Plate CO 326-FTM
Description Silver 1993 Toyota Pickup Base V6 3.0L 2959C
VIN V
VIN JT4VN13D5P5118232
Odometer 256,256 In / 0 Out

Appointment 7/23/2021 8:00 AM
Promised 7/23/2021 6:00 PM

Concern

Fluid Leak, Steering / Suspension

Concern? = power steering is leaking - this has been going on for years.

Inspection

Preventive Maintenance Inspection

45 Point Maintenance Inspection - Provided complementary to give a general overview of the condition of the vehicle.

Labor \$0.00 *
Sub \$0.00

-- Inspection Results from AutoVitals SmartFlow --
Preventative Maintenance Inspection, rev. 1
<https://motorist.autovitals.com//EDK1Ta>

Service

Diagnose Steering Concern

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor \$62.50 *
Sub \$62.50

-- Technician Notes from AutoVitals SmartFlow --
There are lots of leaks. I believe the power steering pump is leaking the most and the sensor on the pump is also leaking. Recommend starting with the power steering pump then re checking for further power steering leaks.

Power Steering Pump & Control Valve

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Remove & Replace Power Steering Pump \$211.25 *
P/S Air Control Valve 1 Unit \$190.96 / Unit \$190.96 *CS
P/S Pump 1 Unit \$349.47 / Unit \$349.47 *CS
Sub \$751.68

Power Steering Fluid Flush with BG Chemicals Kit

Connect flush equipment to remove existing fluid. This service includes a BG Chemicals cleaner to break up and help remove gum and varnish deposits in the power steering system and a specially formulated synthetic fluid containing anti-wear agents, anti-oxidants and seal conditioners. Fill system to proper capacity with new fluid after flush.

Professional Technical Service
BG 108/332R 1 Unit
Sub \$144.78

Lube, Oil & Filter Service - Conventional Oil

1) Drain oil and replace with proper weight and quantity conventional oil as requested. (Up to 5 Quarts)

2) Install new premium oil filter.

3) Lubricate chassis and drive shaft universal joints if equipped/accessible.

4) Top up levels of power steering, wiper washer fluid, coolant and transmission fluid if needed.

-- Added by SmartFlow on 7/23/2021 --

Professional Technical Service			\$15.00 *
PENNZOIL SAE 10W30	4.4 Unit	\$5.90 / Unit	\$25.96 *CS
GOLD OIL FILTER	1 Unit	\$10.18 / Unit	\$10.18 *CS
		Sub	\$51.14

Timing Belt With Water Pump

Remove and Replace components as required to access and install timing belt kit. Additional fluids may be required to complete this service. Replacement of the timing belt includes; new timing belt, tensioner, idler pulleys and water pump as needed. Perform final road test after repairs and verify coolant level.

-- Added by SmartFlow on 7/23/2021 --

Remove & Replace Timing Belt			\$817.50 *
* Remove & Replace Timing Belt Idler Pulley			
* Remove & Replace Timing Belt Idler Pulley			
* Remove & Replace Timing Belt Tensioner			
Timing Component Kit and Water Pump - AISIN	1 Unit	\$444.47 / Unit	\$444.47 *CS
GREEN COOLANT	2 Unit	\$14.98 / Unit	\$29.96 *CS
		Sub	\$1,291.93

Manual Transmission Fluid Exchange

Remove existing fluid. Fill system to proper capacity with new fluid meeting OE specifications. Fluid additives and/or conditioners may be required.

-- Added by SmartFlow on 7/23/2021 --

Professional Technical Service			\$100.00 *
SYN GEAR LUBE 75W-90	6.4 Unit	\$11.48 / Unit	\$73.47 *CS
		Sub	\$173.47

Front Differential Fluid Exchange

Drain and fill differential as needed.

-- Added by SmartFlow on 7/23/2021 --

Professional Technical Service			\$62.50 *
SYN GEAR LUBE 75W-90	3.4 Unit	\$11.48 / Unit	\$39.03 *CS
		Sub	\$101.53

Transfer Case Fluid Exchange

Drain and refill system to proper capacity with new fluid meeting specifications specified by the manufacture.

-- Added by SmartFlow on 7/23/2021 --

Professional Technical Service			\$62.50 *
SYN GEAR LUBE 75W-90	3.4 Unit	\$11.48 / Unit	\$39.03 *CS
		Sub	\$101.53

Rear Differential Fluid Exchange

Drain and fill differential as needed.

-- Added by SmartFlow on 7/23/2021 --

Professional Technical Service			\$62.50 *
SYN GEAR LUBE 75W-90	4.6 Unit	\$11.48 / Unit	\$52.81 *CS
		Sub	\$115.31

Fuel Filter

Remove and Replace components as required to access and install new fuel filter.

-- Added by SmartFlow on 7/23/2021 --

Remove & Replace Fuel Filter			\$100.00 *
Fuel Filter - NAPA Gold	1 Unit	\$35.98 / Unit	\$35.98 *CS
		Sub	\$135.98

Shock Absorber, Both Front

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 7/23/2021 --

Remove & Install or Remove & Replace Front Shock &/Or			\$195.00 *
---	--	--	------------

Strut Assembly - Both			
Shock - MonoMax - Front	2 Unit	\$125.67 / Unit	\$251.34 *CS
		Sub	\$446.34

Shock Absorber, Both Rear

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 7/23/2021 --

Remove & Install or Remove & Replace Rear Shock &/Or Strut Assembly - Both			\$130.00 *
--	--	--	------------

Shock - MonoMax - Rear	2 Unit	\$130.95 / Unit	\$261.90 *CS
		Sub	\$391.90

Total Parts		\$1,886.84
Total Labor		\$1,881.25
Total Before Taxes & Miscellaneous Charges		\$3,768.09

(*) Environmental/ Hazmat / Supply Fee		\$49.82 C, S
(C) City Sales Tax	4.11 %	\$79.60
(S) State Sales Tax	2.9 %	\$56.16
Grand Total		\$3,953.67

I hereby authorize the repairs to be done along with the required materials and agree that Phil's Pro Auto Service and its Agents are not responsible for loss or damage to the vehicle or contents in the case of fire or theft or causes beyond their control. I hereby grant Phil's Pro Auto Service and its Agents permission to operate the vehicle on the streets and highways or elsewhere for the purpose of testing and or inspection. I acknowledge my indebtedness for the amount of this invoice and acknowledge and agree that in the event of non-payment that the repairer is entitled to liens under any applicable Repair Liens or Storage Liens Legislation. This information and any other information Phil's Pro Auto Service has in its database is restricted to authorized personnel only. This information will be used solely for the current and future service of my vehicle, warranty registration, and any other use required by law. I have a right to a written estimate. A repairer may not charge an amount that is more than ten (10) per cent above that estimate. If I waived my right to an estimate, Phil's Pro Auto Service must have my authorization of the maximum amount that I will pay for the repairs. Phil's Pro Auto Service may not charge more than the maximum amount I authorized. In either case, Phil's Pro Auto Service and its Agents may not charge for any work I did not authorize. A storage charge of \$10 per day will be charged if vehicle is not picked up within three business days after the owner has been notified.

Customer Signature: _____